

# Results of I-V Curves and Visual Inspection of PV Modules Deployed at TEP Solar Test Yard

Peter McNutt, John Wohlgemuth,  
David Miller, Blaise Stoltenberg – NREL

## Background

- The purpose of the PV Service Life Prediction project is to examine & report on how modules fielded 5 or more years are holding up
- Testing performed January 13-16, 2014
- NREL compared test results to 2012 testing performed by University of Tucson (Kopp, et. al.) as well as against STC nameplate ratings
- Details of module tests from three manufactures are presented
- Present the common problems crystalline-silicon and thin-film modules exhibit



## Test Method

- Perform visual inspection (per Packard 2012 paper)
- Take IR images
- Take photos
- Take I-V traces




## Test Equipment



- Solmetric PVA-600 PV analyzer
- 600 Vdc and 20 Adc
- Capacitive load
- Operating temperature -0°C to 50°C
- ~ \$5000

- Type K thermocouple
- 1.0°C resolution and accuracy
- Range -100°C to 200°C
- Wireless connection to PVA-600
- Field measurements include performance factor of PV modules or strings (measured / expected)



- Reference cell – IMT Solar
- monocrystalline
- cell embedded in EVA between glass & Tedlar
- active temperature compensation
- 0 to 1500 W/m<sup>2</sup> range
- Operating temperature -20°C to 70°C
- +/- 5% typical accuracy
- Wireless connection to PVA-600





- FLIR T440 IR camera
- 320 x 240 pixel resolution
- < 0.045 thermal sensitivity
- Temperature range -20°C to 1200°C
- 7.5 to 13um spectral range
- ~ \$11,000

## Manufacturer A



- Crystalline Si
- Deployed ~ 2003
- Glass superstrate and polymeric backsheets
- All 16 modules have bubbles in backsheets
- Discoloration pattern around j-box, parallel bus lines, and cell edges




- In 2014, measured values divided by nameplate ratings were 44% and 94% for 2 modules
- In 2012 Kopp paper, the rating ranged from 44% to 94% for 8 modules

- Module Nameplate Ratings:
- Pmp = 180 W • Imp = 3.33A
- Voc = 66.4V • Vmp = 54V
- Isc = 3.65A

Model • Sandia  
Irradiance: 845.1 W/m<sup>2</sup>  
T backside: 44.4 °C


## Manufacturer C

- Crystalline Si Module
- glass superstrate and polymeric backsheets
- Deployed 2006
- String I-V performance ranged between 78% to 89% (measured 2 strings of 9 modules – range was 58% to 89% in 2012 Kopp paper measuring 9 individual modules)
- Observed hot spots on 2 out of 18 modules



- 65% of nameplate rating I-V trace – 9 module string

- String STC Nameplate Ratings (9 modules):
- Pmp = 1521 W • Imp = 4.77 A
- Voc = 388 V • Vmp = 311 V
- Isc = 5.46 A



## Major Visual Observations

### Crystalline-Silicon modules

most have glass superstrates and polymeric backsheets

(manufacturer)

- D. 9 modules, deployed 2004 – 8 modules have typical EVA browning (1 recent replacement); All have loose j-box lids; Labels have fallen off all modules. Output (I-V) of 3 modules – 82% of nameplate rating (see photo 1)
- E. 10 modules, deployed ~2003 – 10 modules show no visible signs of defects. 2 modules – 76% of nameplate.
- F. 8 modules, deployed ~ 2000) – all show typical EVA browning. No I-V taken.
- G. 15 modules, deployed 2009 – 1 module had burn mark on the back; all modules have frame adhesive oozing out of frames onto module front. No I-V taken.
- H. 9 modules, deployed 2003 – no visual defects. 2 modules – 72% of nameplate.
- I. 8 modules, deployed 2003 – All modules had some bubbles and ridges between cells in backsheets; EVA discoloration. 3 modules – 72% of nameplate.
- J. 20 modules, deployed 2000 – Typical (but not pronounced) EVA discoloration. 3 modules – 69% of nameplate.
- K. 72 glass-on-glass modules, deployed ~2001 – All have delamination above j-boxes; 6 modules have delamination in a corner or at an edge with subsequent corrosion of metallization. No I-V taken. (see photo 3)

### Thin-film modules

- L. CIS, glass-on-glass, (deployed ~ 2003) – 2 of 20 modules removed (due to broken glass); Remaining modules had no visual defects. 2 modules – 76% of nameplate
- M. CIGS, polymeric front & backsheets with discreet cells (deployed ~ 2003) – Some curling of substrate and delamination of superstrate. 1 module – 76% and 1 module – 55% of nameplate.
- N. a-Si, glass/glass (deployed ~ 2004) – 1 of 150 had broken back glass; Corrosion around junction box contact feed through area on all modules; About 2/3rds of the modules had bar graph corrosion in lower corners. 4 module – 63% of nameplate. (see photo 2)

## References


- TEP Solar Test Yard PV Site Visit - 2013/2/05, David Miller, NREL, April 2013.
- I-V Curves and Visual Inspection of 250 PV Modules Deployed over 2 Years in Tucson, Emily S. Kopp et al, University of Arizona, Tucson, 2012.
- Development of a Visual Inspection Data Collection Tool for Evaluation of Fielded PV Module Condition, Corinne Packard et al, NREL, August 2012.
- PV SYSTEM REPORTS AT THE TEP SOLAR TEST YARD – available at [http://uapv.physics.arizona.edu/ncdfs/teptestyard\\_field\\_IVcurves.pdf](http://uapv.physics.arizona.edu/ncdfs/teptestyard_field_IVcurves.pdf)
- Historic data for the TEP Solar Test Yard site is also available on the website <http://uapv.physics.arizona.edu/dpivdata.php>

The authors would like to thank Adria Brook (U of AZ) and Randy Hunsberger (NREL),  
Work done under DOE Agreement # DE-AC36-08G028308

## Manufacturer B




- Crystalline Si Module –
- glass superstrate and polymeric backsheets
- deployed 2005
- 1 out of 18 modules had burn mark on back which was also visible on front of cell
- Evidence of overheating at output lead solder bond (6 out of 18)
- IR image detected module with 2 rows of hot cells – I-V trace found module output to be 56% of expected
- Performance range for this module was not reported in 2012 Kopp paper



comparison of "bad" (56%) and "good" (88%) modules

- Module STC Nameplate Ratings:
- Pmp = 170 W
- Voc = 44 V
- Isc = 5.4 A
- Imp = 4.9 A
- Vmp = 34.7 V



## Conclusions

- IR images quickly detect problems
- Visual inspection after IR image usually determines the exact cause of problem
- Testing should be done by teams of two or more people working closely together
- Best procedure would be to scan arrays & modules first with an IR camera, then take visual photos and I-V traces
- Major visual defects included EVA browning, delamination, burn marks, oozing adhesive, backsheets bubbles, and broken glass.
- Some modules show no signs of visual defects
- Overall, after being deployed from 4 to 12 years, the modules were found to be operating fairly well, still delivering from 55% to 82% of their nameplate rating

- NREL is looking for other older PV systems to do testing & analysis
- Contact: Peter McNutt | [peter.mcnutt@nrel.gov](mailto:peter.mcnutt@nrel.gov) | 303 384 6767