### ELEVATIONS OF BENCH MARKS, OBSERVATION WELLS, AND PRODUCTION WELLS AT MATHER AIR FORCE BASE, SACRAMENTO COUNTY, CALIFORNIA, 1988

By M.E. Ikehara, W.F. McCaffrey, and J.S. Williams

U.S. GEOLOGICAL SURVEY

Open-File Report 88-716

Prepared in cooperation with the U.S. DEPARTMENT OF ENERGY AND U.S. AIR FORCE, AIR TRAINING COMMAND



DEPARTMENT OF THE INTERIOR DONALD PAUL HODEL, Secretary U.S. GEOLOGICAL SURVEY Dallas L. Peck, Director

For additional information write to:

District Chief U.S. Geological Survey Federal Building, Rm W-2234 2800 Cottage Way Sacramento, CA 95825 Copies of this report may be purchased from:

U.S. Geological Survey Books and Open-File Reports Federal Center, Bldg. 810 Box 25425 Denver, CO 80225

# CONTENTS

	Page
Abstract	. 1
Introduction	, 2
Surveying procedure and accuracy	. 2
Elevations of bench marks	, 9
Elevations of observation and production wells	. 9
Summary	. 16
Reference cited	. 16

# ILLUSTRATIONS

\_\_\_\_\_

		1	Page
Figure	1.	Map showing primary network of survey lines, bench marks	
		with historic data, and new bench marks for which	
		elevations were obtained in June 1988	4
	2.	Map showing observation and production wells for which	
		elevations were obtained in June 1988	6

### TABLES

- -----

			Page
Table	1.	Summary of level closures for the five survey lines comprising the primary network	8
	2.	Elevations determined from this survey and previous	
		leveling surveys for selected bench marks	10
	3.	Elevations and descriptions of new bench marks	11
	4.	Elevations and descriptions of runway reference marks	12
	5.	Elevations of measuring point for observation wells	13
	6.	Elevations of measuring point and/or reference point of	
		production wells, and adjacent land surface	14

#### **CONVERSION FACTORS**

For use of readers who prefer to use International System (SI) units, rather than the inch-pound terms used in this report, the following conversion factors may be used:

#### Multiply

<u>Ву</u>

\_

#### To obtain

foot (ft)
mile (m)
inches (in.)

0.3048 1.609 25.40 meter (m) kilometer (km) millimeter (mm)

### ELEVATIONS OF BENCH MARKS, OBSERVATION WELLS, AND PRODUCTION WELLS AT MATHER AIR FORCE BASE,

SACRAMENTO COUNTY, CALIFORNIA, 1988

By M.E. Ikehara, W.F. McCaffrey, and J.S. Williams

#### ABSTRACT

Precise and accurate elevations of water-level-observation wells on Mather Air Force Base near Sacramento, California, were needed to determine the direction of ground-water flow at and near the base. A total of 19 miles of primary survey lines were run on or near Mather Air Force Base. The datum of these surveys is based on National Geodetic Survey bench mark Y952 about 1.5 miles south of the base at the intersection of Jackson Highway (State Route 16) and Excelsior Road. The accuracy of these levels, based on National Oceanic and Atmospheric Administration standards, ranged between first and third order. Elevations of 41 bench marks, 76 observation wells, and 15 production wells on Mather Air Force Base were determined by differential leveling during June 1988. Levels were run to a designated measuring point on observation wells, to the pressure valve of production wells, to the land surface adjacent these wells, and to selected bench marks, some of which are on runways or taxiways.

#### INTRODUCTION

This report documents the elevations of 41 bench marks, 76 observation wells, 14 active production wells, and 1 former production well (figs. 1 and 2). Fourteen of the 41 bench marks were recently installed on Mather Air Force Base near Sacramento, California. This study was done by the U.S. Geological Survey, in cooperation with the U.S. Department of Energy and U.S. Air Force, Air Training Command, as part of the Installation Restoration Program. The Installation Restoration Program has the objectives of identifying, evaluating, and mitigating potential problems caused by past handling and disposal of toxic/hazardous materials at Air Force facilities. The ultimate goal of the program is to prevent movement of any toxic or hazardous materials into areas where health and property could be endangered.

One aspect of the Installation Restoration Program is to determine flow directions of shallow ground water by measuring depth to the water table at observation wells. Because of the small topographic relief near the base, precise and accurate elevations of the measuring point on the wells are required.

The purpose of this study was to determine elevations of various bench marks, observation wells, and production wells on the base to a common datum; in this case, the National Geodetic Vertical Datum of 1929. In addition, a number of bench marks on runways and taxiways were included in the level network.

Surveying on the base was accomplished through the efforts of several individuals. Access to sensitive areas on the base and to the observation wells was facilitated by Lt. Col. Richard Blank of the Environmental Management Section. Mr. Richard Udell, Base Surveyor, served as liason between base security, SAC security, and the surveying crews, provided information on existing base bench marks, and helped install new bench marks on the base.

#### SURVEYING PROCEDURE AND ACCURACY

The differential leveling surveys were completed during June 1988 with most of the work completed during the morning hours. Field weather conditions, such as temperature and wind, generally were moderate during the survey period and tended to reduce the magnitude of error caused by refraction, and expansion and contraction of survey rods.

Equipment used in the surveys included the Zeiss Ni2<sup>1</sup> automatic compensating level, maintained in adjustment, and Philadelphia rods of the Lietz Precise Series. Foresight and backsight distances were balanced to reduce collimation error.

2 Elevations of Bench Marks and Wells, Mather Air Force Base, California


<sup>&</sup>lt;sup>1</sup>Use of brand names in this report are for identification purposes only and does not constitute endorsement by the U.S. Geological Survey.

Bench marks used were previously established by the National Geodetic Survey, U.S. Engineering Department, and the U.S. Bureau of Reclamation. All elevations for the U.S. Geological Survey 1988 leveling surveys are based on the elevation of National Geodetic Survey bench mark Y952, which was established in 1962 and is about 1.6 miles south of bench mark HG-1 (fig. 1). Bench mark Y952 is in the top of the concrete head wall of double box culvert A-5.92, southwest of the intersection of Jackson Road (State Route 16) and Excelsior Road. Bench mark Q955 is set vertically in the center of the north face of the concrete porch of the building at 9978 Folsom Boulevard. This bench mark, also established in 1962 by National Geodetic Survey, was leveled to but was found disturbed. Thus, it was not used in setting the datum for the Geological Survey 1988 leveling surveys because the concrete porch had cracked and settled.


A total of 19 miles were surveyed to form the primary network (fig. 1). Survey line A, to the south, and line B, to the north, originated from bench marks off the base. Line C, comprised of seven segments, totaled 8.94 miles. Segment D2, 1.26 miles, was part of line D that was 3.55 miles in length. Segment E6, 0.80 mile, was part of line E that was 2.92 miles in length. Because segment D2 was adjusted on the basis of the closure of line D, 1.26 miles was subtracted from 8.94 miles, line C's total length. The other segments of line C were then adjusted for a difference of 0.087 foot in closure for the remaining 7.68 miles.

The National Oceanic and Atmospheric Administration, Federal Geodetic Control Committee (1980) (formerly National Geodetic Survey) has defined standards of accuracy for vertical-control surveys. These standards are based, in part, on the distance surveyed. The maximum closures for survey lines are computed as follows: Second order, class  $I--6mm\sqrt{K}$ ; second order, class  $I--6mm\sqrt{K}$ ; and third order--12  $mm\sqrt{K}$ , where K equals one-half the total survey line distance, in kilometers.


The accuracy of the U.S. Geological Survey 1988 leveling surveys is based on closure differences for the survey lines. Lines C and E are third order, and lines A, B, and D are better than third order standard of accuracy. Closure differences ranged between 0.001 and 0.087 foot and had an absolute average of 0.032 foot. Adjustments for the various survey line and segment closures were based on line length. A summary of the level closures for the five survey lines comprising the primary network (fig. 1) is given in table 1. Once the primary network was established, levels to the observation wells, the production wells, and other bench marks were run as closed survey lines from the primary network. Locations of observation and production wells are shown in figure 2.



4 Elevations of Bench Marks and Wells, Mather Air Force Base, California







6 Elevations of Bench Marks and Wells, Mather Air Force Base, California




FIGURE 2. Observation and production wells for which elevations were obtained in June 1988.

Survey line (fig. 1	line	Survey line name	Survey line segment length (miles)	Total survey line length (miles)	Closure (foot)
A		Y952 to TBM Spike and return		3.35	+0.004
В		Q955 to 101-221 and return		2.2	+.004
С	C1 D2	TBM Spike to H-MB-NE H-MB-NE to MD-NE	0.61 <sup>1</sup> 1.26		
	C3 C4	MD-NE to RM17 RM17 to 101-221	1.34		
	C5	101-221 to TP36	3.48		
	E6 C7	TP36 to TP12 TP12 to TBM Spike	<sup>1</sup> 0.80 0.50		
	Total for 1	line C segments only		6.88	.087
D		MB-NE to MD-NE to MB-NE		3.55	+.001
Е		TP12 to TP36 to TP12		2.92	063

### **TABLE 1.--Summary of level closures for the five survey lines**comprising the primary network

 $^{\rm l} {\rm These}$  segment distances are included in totals for lines D and E, as applicable.

#### **ELEVATIONS OF BENCH MARKS**

Elevations determined from this survey and previous leveling surveys for selected bench marks are shown in table 2. Elevations for previous leveling surveys were furnished by Mather Air Force Base, private contractors, and other Federal agencies. Bench mark X744 was found slightly damaged, in that its surface was scratched and dented. Bench mark 101-101, northeast of the merging of Lower Placerville Road and Hoffman Street, was found with its concrete base lying at a 45 degree angle; therefore, it was not included in the leveling network. Bench mark 396+50 is a U.S. Bureau of Reclamation bench mark set in November 1972 at milepost 7.5 of the Folsom South Canal.

Fourteen bench marks were established on June 7, 1988, by the U.S. Geological Survey and the Base Surveyor, four of which are on the base runways. Elevations and descriptions of these new bench marks are given in table 3. Other reference marks on the runway are described in table 4, which also lists the elevations obtained in 1988.

#### ELEVATIONS OF OBSERVATION AND PRODUCTION WELLS

The primary objective of this study was to determine the elevation of the point to which water-level measurements are referenced, known as the measuring point. For observation wells, the measuring point was identified by two hacksaw-cut grooves cut in the top of the steel casing. The hacksaw grooves had been established earlier and often were marked with white paint. The measuring point for wells where the casing was finished below grade was two hacksaw-cut grooves in the flange of a steel ring (for the cover plate), cemented in place flush with the land surface. Elevations of each measuring point for 76 observation wells are shown in table 5. Data furnished from previous surveys also are shown, with the caution that these elevations may not necessarily be for the same place on the well, because the designated measuring points were established just prior to this survey.

The measuring point of production wells generally was a pressure line valve, which usually could not accommodate a survey rod owing to its location with respect to the pump and motor assembly. In such a situation, a reference point near the measuring point was surveyed to, and the difference between the two points was measured to determine the elevation of the measuring point. The elevations of the measuring point and/or reference point, and adjacent land surface for the production wells are given in table 6. A former production well, designated AC&W, no longer has a designated measuring point.

TABLE 2Elevation	s determined fro	om this survey	and previous
leveling s	urveys for selec	eted bench ma	rks

[USGS, U.S.	Geologi	ical	Survey;	MAFB,	Mather	Air	Force	Base;	
	USED, U	J.S.	Engineer	ring De	epartmer	nt]			

		Elevation	ns, in feet	
Bench mark (fig. 1)	USGS 1988	MAFB	Private contractor	Other Federal agencies
¥952				<sup>1</sup> 88.648
Q955				71.174
101-020	118.92	118.98	119.15	
101-066	125.67	125.74	125.74	
101-067	123.84	123.90		
101-072	82.37		82.44	
101-075	81.60		81.67	
101-142	128.62	128.70		
101-143	149.43	149.53	149.53	
101-144	150.20	150.29	150.29	
101-208	78.80	78.90		
101-215	79.96	80.06		
101-221	88.54	88.55		
101-222	88.52	88.52		
101-223	90.69	90.71		
101-227	72.34			
101-228	72.38			
101-229	73.27			
101-249	81.59			
X744	94.25	94.35	94.34	<sup>2</sup> 94.31
ALEX	76.90		77.00	
USED 9578 (S-760)	85.63	85.75	85.72	
USED WT	85.67	85.65		
USED 6&G	86.99	87.05	87.05	
USED G&G	88.90			
396+50	142.88			<sup>3</sup> 142.90

Elevations, in feet

<sup>1</sup>National Geodetic Survey bench mark on which leveling is based.
<sup>2</sup>U.S. Engineering Department bench mark, National Geodetic Survey value from 1st order survey, 1944-45.
<sup>3</sup>U.S. Bureau of Reclamation.

Bench mark (fig. 1)	Elevation (feet)					
HG-1	87.56	Brass tablet on southeast end of Mather Boulevard bridge over Morrison Creek, near south entrance to base, Wherry Housing Gate. Stamped HG-1.				
H-MB-NE	113.75	Brass tablet on sidewalk at northeast corner, intersection of Mather Boulevard and Branch Drive West. Stamped H-MB-NE.				
H-MCH-SE	103.83	Brass tablet on concrete pad for manhole cover at southeast corner, intersection of Mather Boulevard and west entrance to Chapel #2. Stamped H-MCH-SE.				
MD-NE	127.82	Brass tablet on concrete headwall of culvert at northeast corner, intersection of Mather Boulevard and Douglas Road. Stamped MD-NE.				
GC-SW	126.58	Brass tablet on southwest corner of bridge abutment on Eagles Nest Road across Morrison Creek at Mather Lake outlet, near entrance to Mather Golf Course. Stamped GC-SW.				
001	140.50	Brass tablet on southwest corner of concrete pad for guardhouse at Douglas Road Gate. Stamped OOI.				
ALICIA	73.85	Brass tablet on northwest side of concrete pad for observation well MAFB-58, which is southeast of gravel pits at southwest corner of base. Stamped ALICIA.				
SAN	75.02	Brass tablet on southeast corner of concrete wall of Sacramento County sewer waste-treatment flow- metering station near southwest end of runway. Stamped SAN.				
QUINN	69.94	Brass tablet 38 feet southeast of center line of Perimeter Road in center of north concrete weir training wall beside enclosure 7100. Stamped QUINN.				
JOHN	67.10	Brass tablet on northwest side of concrete pad for observation well MAFB-59, which is across road from jet test cell near southwest corner of base. Stamped JOHN.				

### TABLE 3.--Elevations and descriptions of new bench marks

Bench mark (fig. 1)	Elevation (feet)	Description				
4R	75.00	Brass tablet at center line of southwest end of runway 4R (22L); southwest side of intersection with taxiway G; 14 feet runway side of threshold. Stamped 4R.				
4L	78.72	Brass tablet at center line of southwest end of runway 4L (22R); southwest side of intersection with taxiway E; 14 feet runway side of threshold and reference mark PK. Stamped 4L.				
22R	91.78	Brass tablet at center line of northeast end of runway 22R, at northeast side of intersection with taxiway B; 14 feet runway side of threshold. Stamped 22R.				
22L	95.97	Brass tablet at center line of northeast end of runway 22L, at northeast side of intersection with taxiway A; 14 feet runway side of threshold. Stamped 22L.				

TABLE 3.--Elevations and descriptions of new bench marks--Continued

TABLE 4.--Elevations and descriptions of runway reference marks

Reference mark (fig. 1)	Elevation (feet)	Description
TACAN	94.61	Painted circle on taxiway A, between northeast ends of runways 22L and 22R.
РК	78.58	Steel pipe driven flush with pavement at center line of southwest end of runway 22R, at threshold; 14 feet southwest of BM 4L.
ARS	82.40	Brass tablet centered between runways 22R and 22L; southwest edge of taxiway D; known as Airport Reference Station. Set by National Geodetic Survey. Stamped ARS 1983.

### TABLE 5.--Elevations of measuring point for observation wells

[See f	Eigure	2	for	location	of	observation	wells]
--------	--------	---	-----	----------	----	-------------	--------

	Elevations, in feet								
Mather			Mather						
Air Force	June 1988	Previous	Air Force	June 1988	Previous				
Base well	survey	surveys	Base well	survey	surveys				
1	131.68		38	77.75	77.79				
2	130.78		39	75.00	75.03				
3	128.04		40	39.54	39.06				
4	173.38		41	73.64	73.16				
5	135.21		42	74.98	74.74				
6	98.34		43	75.15	74.97				
7	74.75		44	76.30	75.49				
8	76.06		45	77.75	76 <b>.94</b>				
9	79.36		46	68.60	68.31				
10	81.11		47	77.24	76.53				
11	80.38		48	75.63	75.32				
12	96.52	96.53	49	92.26	91.47				
13	92.21	91.89	50	124.34	123.43				
14	92.45	92.59	51	126.72	126.35				
15	92.12	92.20	52	123.78	122.08				
16	120.04	120.04	53	131.33	133.43				
17	121.66	121.66	54	118.68	117.70				
18	119.78	119.68	55	40.03	39.19				
19	131.40	131.41	56	74.17	73.40				
20	127.00	127.06	57	75.34	74.38				
21	127.79	127.77	58	75.52	74.60				
22	132.67	137.95	59	69.62	69.10				
23	132.42	132.52	60	77.48	76.90				
24	126.80	126.67	61	78.43	78.13				
25	125.41	125.89	62	80.06	78.99				
26	122.80	122.83	63	76.09	75.08				
27B	147.93	147.96	64	132.38	123.30				
27C	147.56	147.58	65	134.28	128.71				
28	135.20	134.79	66	93.51	93.03				
29	131.27	130.71	67	129.41	129.08				
30	134.25	133.90	68	131.44	130.77				
31	92.98	93.01	69	133.87	133.40				
32	93.53	93.33	70	123.60	123.51				
33	80.88	80.81	71	131.48	128.22				
34	81.33	80.97	72	117.07	116.95				
35	80.65	80.14	73	92.76	92.67				
36	82.27	81.85	75	133.42	127.38				
37	78.82	78.63	76	132.92	123.33				

### **TABLE 6.**--Elevations of measuring point and/or reference point of<br/>production wells, and adjacent land surface

[MP, measuring point; RP, reference point; LS, land surface]

Production well	Designation	Elevation (feet)	Description
Base 1	MP	92.93	Top of pressure line valve
	RP	92.18	Temporary point on building floor
	LS	92.0	
Base 2	MP	92.32	Top of pressure line valve
	RP	92.18	Concrete pad
	LS	91.0	
Base 3	MP	92.74	Top of ½-inch pipe elbow with sealant securing the flexible pressure line
	RP	92.34	Concrete pad below ½-inch pipe elbow
	LS	90.5	
Base <b>4</b>	RP	95.69	Surveyed top of $\frac{1}{4}$ -inch steel plate bolted to pump housing, with gauge fitting welded to other end of plate
	LS	93.3	
FH-1	МР	113.51	Surveyed top of 1-inch steel bracket bolted to pump housing. (Gauge is attached to movable pressure line, thus not surveyed.)
	LS	110.9	-
FH-2	MP	103.60	Top of pressure line valve
	RP	103.19	Concrete pad
	LS	101.8	
FH-3	MP	122.63	Surveyed top of pressure line valve
	LS	119.6	·

# TABLE 6.--Elevations of measuring point and/or reference point of<br/>production wells, and adjacent land surface--Continued

[MP, measuring point; RP, reference point; LS, land surface]

Production well	Designation	Elevation (feet)	Description
FH-4	MP	112.93	Top of pressure line valve
	RP	112.14	Concrete pad
	LS	110.6	
FH-5	MP	124.51	Surveyed top of pressure line valve
	LS	121.5	
FH-6	MP	115.59	Top of pressure line valve
	RP	114.43	Top of bolt on concrete pad
	LS	112.8	
GC-1	MP	126.25	Surveyed top of 2-inch pipe set at an angle on the east side of concrete pad
	LS	124.0	-
GC-2	MP	139.41	Surveyed top of pressure line valve
	LS	137.7	
K-9	MP	151.25	Top of horizontal pressure line valve
	RP	151.44	Top of carpenters level placed on horizontal pressure line valve
	LS	149.9	pressure rine varve
JTC	МР	70.62	Surveyed top of horizontal pressure line valve
	LS	69.1	-
AC&W	RP	134.64	Surveyed top of 1-inch
(former)			diameter circular steel protrusion on west side of 5-inch diameter discharge pipe to south wall. (Pressure line is movable, thus not surveyed.)
	LS	133.2	chus not surveyeu.)

#### SUMMARY

Knowledge of the depth to the water table at Mather Air Force Base is an integral part of the Installation Restoration Program. Measurements made at water-level-observation wells and production wells on the base rely on accurate determinations of the elevations of the measuring points of these wells. Differential surveying produced accurate elevations for 76 observation wells, 15 production wells, and 41 bench marks on Mather Air Force Base, all tied to a common datum--the elevation of bench mark Y952, published in 1962.

#### **REFERENCE CITED**

National Oceanic and Atmospheric Administration, Federal Geodetic Control Committee, 1980, Classification, standards of accuracy, and general specifications of geodetic control survey: 12 p.